

Optical Fibre Inspection & Cleaning Toolkits

Optimal's Inspection & cleaning toolkit includes all the necessary tools to allow the operator to inspect connector ferrule ends both in and out of an adaptor and to clean the ferrule ensuring clean and reliable connections

OPT-5002N Inspection & Cleaning Toolkit includes:

- LCD Microscope with 200x or 400x magnification
- Visual Fault Locator - 1mW
- Fibre Connector Cleaner
- Pen Style Hux Cleaners - 1.25m and 2.5mm styles
- Alcohol Pump Bottles
- Cleaning Sticks
- Hard Carry Case



OPT-5008 Optical Fibre LCD Microscope

LCD microscope as in the OPT-5002N inspection & Cleaning Tool without the accessories

Specifications

Display	TFT 220K LCD 3.5"
AV Output	PAL
Magnification	220X / 400X
Operating Temperature	-10°C to +50°C
Storage Temperature	-20°C to +60°C
Power	12V rechargeable / 6hr continuous use
Dimensions	Monitor: 205 x 94 x 25mm Microscope: 23mm diameter x 160mm
Adaptor tips	2.5mm - for 2.5mm ferrules 1.25mm - for 1.25mm ferrules In adaptor tips to suit: FC, SC, ST, LC



Ordering Details

OPT-5002N-200	Inspection & Cleaning Toolkit (200X)
OPT-5002N-400	Inspection & Cleaning Toolkit (400X)
OPT-5005N-200	Inspection Microscope only (200X) (tips included)
OPT-5005N-400	Inspection Microscope only (400X) (tips included)

Optimal Cable Services Pty. Ltd.

100 Olympia Street
Tottenham, Victoria, 3012

Ph: 03 9316 8300 / Fax: 03 9314 1722

Email: sales@optimal.com.au
Web: www.optimal.com.au

Cable & Connectivity Sales

Vic : 0430 494 022 - Murray Meltzer
: 0412 361 281 - Paul Cross

NSW : 0400 122 738 - Mike Cotie
: 0422 651 321 - Martin Prendergast

Qld : 0414 701 292 - Eric Brace
: 0407 630 429 - Ian Lee

WA : 0407 630 429 - Ian Lee

SA : 0412 361 281 - Paul Cross

Tas : 0430 494 022 - Murray Meltzer

NZ : +61-412-361-281 - Paul Cross